LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M E M Y P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 6 5 EICENSE CODE 14 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T SOURCE L 6 0 5 0 0 0 0 3 0 9 7 0 6 1 2 8 1 8 0 7 0 8 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Reactor plant in refueling shutdown mode, it was found that the Primary Vent Stack 1
Continious Particulate Filter was not installed for the period between 6/12/81 at
1100 hours and 6/16/81 at 1130 hours. Consequently for the above period, Gross
B, f, gross fo individual gamma emitters, and Sr-89 and Sr-90 results are not
available. Primary Vent Stack APD was operational during this period and showed
no increase from normal, therefore, there was no effect on public health and
Safety. Safe
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER ACTION FUTURE COMPONENT SUBMITTED FORM SUB. SUPPLIER SUPPLIER SUBMITTED FORM SUB. SUBMITTED FORM S
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Investigation by the Chemistry department determined that the particulate filter
was not replaced following the previous sample period. Personnel involved have
been reinstructed on the proper procedure.
13
14
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 H 28 0 0 0 29 NA B 31 surveillance test
7 8 9 10 12 13 44 45 46 80 ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 NA NA NA NA
7 8 9 10 11 44 45 80 PERSONNEL EXPOSURES
1 7 0 0 0 37 Z 38 DESCRIPTION (39) NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
1 9 Z 40253 810708 PDR ADDCK 05000309
ISSUED DESCRIPTION (45) NA NA NA NA NA NA NA NA NA N
NAME OF PREPARER Wilbur J. Paine PHONE (207) 882-6321