

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | Z | I | S | I | 0 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T REPORT SOURCE L 0 5 0 0 0 2 9 5 7 0 2 0 4 8 1 8 0 7 1 7 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 | During SS operation, as a result of an inspection due to previous LER
0 3 | micro-switch 2FIC-611A was found to be defective. This switch controls
0 4 | the only valve on the B RHR recirc. line and during a LOCA it would
0 5 | have stayed open, thereby reducing flow required for SI by about 10%.
0 6 | This makes the B RHR train unable to perform its intended function and
0 7 | thus in a degraded mode per T.S. 3.8.3.B. Since the A RHR train was op
0 8 | erable, the health and safety of the public were not affected.

0 9 | SYSTEM CODE C F 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE S 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 1 EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 0 0 4 OCCURRENCE CODE 0 3 REPORT TYPE X 1 REVISION NO. 1
ACTION TAKEN G 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER N 25 CO. INVENT MANUFACTURER B 0 8 0 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
1 0 | Procedure used to check the calibration of these switches was found to
1 1 | be faulty. Procedure was revised and switches tested out satisfactorily
1 2 | during subsequent surveillance. This was not a real problem originally
1 3 | but only appeared to be as a result of the test procedure. Recurrence
1 4 | of this problem is resolved and no further action is necessary.

1 5 | FACILITY STATUS H 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Refueling Surveillance 32

1 6 | ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

1 7 | PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

1 8 | PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

2 0 | PUBLICITY ISSUED N 44 DESCRIPTION NA 45

8107240326 810717 PDR ADJCK 05000295 S PDR

USE ONLY