LICENSEE EVENT REPORT

EXHIBIT A

EARIBIT A
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 A RA NO 1 20 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 4 5 6 17 CAT 58
CON'T O 1 SOURCE L C O O O O O O O O O
During Power Operation, the Sodium Hydroxide Tank, T10, level fell below
the Tech Spec required 33.2 feet during the execution of the Spray Pump,
P35A, Surveillance Test. Samples were immediately taken to determine
ols makeup requirements. Minimum level on T10 was 31.8 feet. There have
ole been no similar occurrences. Reportable per T.S. 6.12.3.2.b.
07
0 8 L 7 8 9
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
SEQUENTIAL REPORT NO. SEQUENTIAL REPORT TYPE NO. 11 22 23 24 26 27 28 29 30 31 11 20
ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER Z] 9 9 9 9 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1] Investigation revealed that the test procedure contained multiple steps
which accumed familiarity with the system layout and functional
idiosyncrasies. The procedure has been revised for clarification. This
Sodium Hydroxide Tank was returned to the required level meeting the
requirements of T.S. 3.3.6.
FACILITY STATUS 1 5 E 28 0 9 9 29 NA OTHER STATUS NA METHOD OF DISCOVERY DESCRIPTION 32 A 31 Operator Observation 80
ACTIVITY CONTENT RELEASED OF RELEASE 1 6 Z 33 Z 34 NA NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA NA NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA NA
PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 0 0 0 140 NA 7 8 9 11 12 12 NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 1 9 Z 42 NA
PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
Chris N Shively (501) 968-2519
NAME OF PREPARER CHIT'S N. SHIVE IS