

TENNESSEE VALLEY AUTHORITY

OFFICIAL COPY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

June 30, 1981

HTRD-50-518, -519, -520, -521/81-02
PBRD-50-553, -554/81-02

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -
PRESSURE DROP IN ESSENTIAL SERVICE WATER PIPING - HTRD-50-518,
-519, -520, -521/81-02 - PBRD-50-553, -554/81-02

The subject deficiency was initially reported to NRC-OIE, Region II, Inspector R. W. Wright on December 10, 1980, as NCR's HTAMEB8001, HTBMEB8001, and PBNMEB8001. The first and second interim reports were submitted on January 12 and March 20, 1981. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the third interim report on the subject deficiency.

TVA underestimated the scope of work necessary to complete this item and we are now finalizing our efforts to resolve this deficiency. We anticipate transmitting the final report on or before July 31, 1981. If you have any questions, please call Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
S/D

8107310242 810630
PDR ADDCK 05000518
S PDR