FORM NRC-591 (3-77)

U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1 LICENSEE			2 REGIONAL DEFICE		
Perry County Memorial Hospital Perryville, Missouri 63775			U.S. Nuclear Regulatory Commission Office of Inspection & Enforcement Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137		
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S		1101S OULS/	
J. DOCKET HOMBER(3)		4. LICENSE NOMBER(S		S. DATE OF INSPECTION	
030-12089		24-17037-01		July 15, 1981	
6. INSPECTION FINDINGS The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:					
No items of noncompliance or unsafe conditions were found.					
The following items of noncomphance related to records, signs, and labels were found:					
A. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42					
B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42					
C. Rooms or ar 10 CFR 20.2	 C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) 				
D. Rooms or an	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)				
E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)					
F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)					
G. FormNRC-3 was not properly posted. 10 CFR 20.206(c)					
H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)					
Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)					
J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51					
K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)					
L. Records of in	L. Records of inventories were not maintained. 10 CFR 34.26				
M. Utilization lo	M. Utilization logs were not maintained. 10 CFR 34.27				
N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24					
O. Recora te	O. Record teletherapy electrical interlock tests were not maintained as prescribed in your license.				
P. Other					
A. S. Trodomo for I Shaffiely					
8108040063 NMS LIC30 24-17037-01	be corrected with	d I understand the item in the next 30 days.		sted above. The items of	
(Date) (Licensee Representative - Title or Position)					