21 JUL 1981

Docket No. 30-5998

State of Washington Department of Social and Health Services ATTN: Nancy Kirner, Supervisor Radiation Control Program Mail Stop LD-11 Olympia, Washington 98504

Dear Ms. Kirner:

Subject: Automation Industries, Inc. (NRC License No. 37-00611-09)

Enclosed is a copy of Office of Inspection and Enforcement Investigation Report No. 30-5998/81-04 documenting an investigation performed by this office following a report that Automation Industries, Inc. received a package with external radiation levels in excess of 200 millirem per hour from Birchfield, Inc. in Bellevue, Washington. Based on the results of the investigations by your and our staffs, we conclude that either the inner seal was not put in place or worked loose during transit allowing the brass plug to unscrew. The source then probably worked into the partially exposed position during transit. Therefore, we conclude the radiation levels were probably highest when the device was accepted by Automation Industries and it is unlikely any significant exposures resulted from this occurrence.

If you have any further questions regarding our investigation report, please feel free to contact me at (215) 337-5252.

Sincerely,

M Costell

John D. l'inneman, Chief Materials Radiological Protection Section

Enclosure: Office of Inspection and Enforcement Investigation Report No. 30-5998/81-04

cc w/encl: Terry Frazee	Public Document Room (PDR) Local Public Document Room (LPDR) Nuclear Safety Information Center	(NSIC)
bcc w/encl: Document Manager	ment Branch, TIDC (For Distribution)	,,
REG:I Reading R OSP		

TIB McGinness/sk1 7/16/81 TIB Kinneman 7/ /81

OFFICIAL RECORD COPY

8108040093 810721 NMS LIC30 37-00611-09 PD PDR

IFOI