ENCLOSURES TRANSMITTED HEREWITH CONTAIN 10 CFR 2.790 INFORMATION

Docket No: 50-293

Boston Edison Company M/C Nuclear ATTN: Mr. A. V. Morisi Nuclear Operations Support Manager 800 Boylston Street Boston, Massachusetts 02199

Gentlemen:

Subject: Inspection 50-293/81-11


This refers to the routine safeguards inspection conducted by Mr. R. J. Bailey of this office on March 30-31, April 1-3, 1981 at Pilgrim Nuclear Power Station. Plymouth, Massachusetts of activities authorized by NRC License No. DPR-35 and to the discussions of our findings held by Mr. Bailey with Mr. R. Machon of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the items of noncompliance brought to your attention in the enclosure to our letters dated October 7 and December 11, 1980. We have no further questions regarding your action at this time.


Based on the results of this inspection, it appears that certain of your activities were not conduced in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. These items of noncompliance have been categorized into the levels described in the Federal Register Notice (45 FR 66754) dated October 7, 1980. You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility security measures for physical protection are deemed to be commercial or financial information within the meaning of 10 CFR 9.5(a)(4) and shall be subject to disc. sure only in accordance with the provisions of 10 CFR 9.12; therefore, the enclosures to this letter, and your response to this letter will not be placed in the Public Document Room and will receive limited distribution.





8108100215 81072



OFFICIAL RECORD COPY

TH

ENCLOSURES TRANSMITTED HEREWITH CONTAIN 10 CFR 2.790 INFORMATION



LE02 5.11

PDR ADOCK 050002 G

Boston Edison Company M/C Nuclear 2

24 JUL 1981

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed By J. H. Joyner

James H. Joyner, Chief, Technical Inspection Branch, Division of Engineering and Technical Inspection

Enclosures:

ALC: NOT

1. Appendix A, Notice of Violation (Contains 2.790(d) Information)

 Office of Inspection and Enforcement Inspection Report Number 50-293/81-11 (Contains 2.790(d) Information)

cc w/encls:

R. D. Machon, Nuclear Operations Manager - Pilgrim Station (w encls) Public Document Room (PDR) (w report cover sheet only), Nuclear Safety Information Center Local Public Document Room(LPDR) (W report cover sheet only) (NSIC) (w report cover sheet Document Management Branch, TIDC (For Distribution) (w/cy of encls) only) REG:I Reading Room (w/report cover sheet only) Commonwealth of Massachusetts (2) (w/report cover sheet only) NRC Resident Inspector (w/encls) Chief, Operational Support Section (w/o encls)

OFFICIAL RECORD COPY

ENCLOSURES TRANSMITTED HEREWITH CONTAIN 10 CFR 2.790 INFORMATION