TENNESSEE VALLEY AUTHORITY

1750 Chestnut Street Tower II. 66

July 31, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE REPORT BFRO-50-296/80060 REVISION 1

The enclosed report is a supplement to my letter dated January 27, 1981 concerning seventeen level switches which would not operate due to dirty floats and one other switch which needed to be replaced. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. Green Director of Nuclear Power

Enclosure (3) cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. P. F. Sullivan, NRC Inspector, Browns Ferry

8108100275 10731 PDR ADDCK 05000296 S PDR 5./1