



GAMMA DIAGNOSTIC LABORATORIES

P.O. BOX 1349

ATTLEBORO FALLS, MASSACHUSETTS 02763

2 June 1981

Docket No. 30-8748

Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Re: License # 20-15215-01MD

Dear Sir,

In accordance with Nuclear Regulatory Commission "Rules of Practice" Part 2, Title 10CFR Section 2.201, we are herewith responding to the notice of violation in Appendix A of your letter of May 19, 1981. Attachment 1 describes the steps which have been taken to correct the violation. Please note that on September 26, 1980 this action was taken and thus full compliance was achieved on that date.

Sincerely,

Vincent. W. DiSpigno, Pharm. D.
Health Physicist

VWD/gb
Enc. Attch. 1

8108100303 810728
NMS LIC30
20-15215-01MD PDR

Attachment 1

Since the actions of the driver involved in the incident of September 25, 1980 were flagrant violations of company policy, the steps taken to correct the violation centered around retraining the driver on the specifics of company policy and Nuclear Regulatory Commission Regulations. The driver was suspended for two days and retrained in proper delivery practices. In addition, a meeting was held with all staff drivers to reinforce the specifics of company policy and Nuclear Regulatory Commission Regulations for proper delivery procedures. These procedures will be stressed in the training of all future drivers.

Respectfully,

Vincent W. DiSpigno, Pharm. D.