

APPENDIX A

NOTICE OF VIOLATION

Public Service Company of New Hampshire
Seabrook Unit 1

Docket No. 50-443
License No. CPPR-135

As a result of the inspection conducted May 26 - June 26, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

10 CFR 50, Appendix B, Criterion V states, in part that: "Activities affecting quality shall be prescribed...and shall be accomplished in accordance with...instructions, procedures, or drawings...(which) shall include appropriate quantitative or qualitative criteria..."

The Seabrook Station PSAR states, in part, in paragraph 17.1.5 that: "Each organization is required to perform their respective quality related activities covered by this program in accordance with documented instructions, procedures, or drawings (which) shall include appropriate quantitative or qualitative acceptance criteria."

UE&C Drawing M300228, SH.C-22 (Revision 2), indicates the typical details for mounting electrical boxes on concrete. Criteria for Hilti anchor spacing are specifically noted, but for anchor location are only pictorially represented.

Contrary to the above, as of June 25, 1981, several electrical boxes in containment mounted in accordance with the noted, but not pictorial, Hilti anchor location requirements of Drawing M300228, SH.C-22, were determined to be improperly supported in that the loads had been attached to unanchored, cantilever extensions of the strut material.

This is a severity Level V Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, Public Service Company of New Hampshire would be required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. However, your corrective action was taken during this inspection period and has been described and verified in the attached inspection report.

Dated JUL 22 1981

/s/ E. J. BRUNNER

Eldon J. Brunner, Chief, Projects Branch
No. 1, Division of Resident and Project
Inspection

OFFICE							
SURNAME							
DATE	8108100323	810722					
	PDR	ADDCK	05000443				
	Q	PDR					