

APPENDIX A
NOTICE OF VIOLATION

Georgia Power Company
Vogtle 1

Docket Nos. 50-424
License Nos. CPPR-108

As a result of the inspection conducted on June 2-6, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified.

10 CFR 50, Appendix B, Criterion V requires that activities affecting quality shall be prescribed by documented procedures and instructions and shall be accomplished in accordance with these procedures and instructions: Procedure CD-T-02, "Concrete Quality Control", paragraph VI.E.7 requires the spacing of concrete vibrator insertions to be approximately 18 inches apart.

Contrary to the above, in the lower one-third of the concrete placement in pour number A-08B-049, vibrator insertions were made through openings in the forms spaced three to five feet apart. The size of the openings and congestion did not allow the spacing of concrete vibrator insertions to be made at the required 18-inch spacing.

This is a Severity Level V Violation (Supplement II.E).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Date: JUN 19 1981