Docket No. 99900747/81-01

CTI - Nuclear Division of McDowell - Wellman Company ATTN: D. J. Beecher Manager of Engineering P.O. Box 5768 Cleveland, Ohio 44101

14

Gent?emen:

This refers to the inspection conducted by H. W. Roberds of this office on March 10-13, 1981, of your facility at Cleveland, Ohio, associated with the fabrication of standby gas treatment systems and to the discussions of our findings with you and members of your staff at the conclusion of the inspection.

This inspection was made as a result of: (1) the issue of a 10 CFR Part 21 report pertaining to the identification of defects in a temperature detection unit type, that had been installed in equipment furnished to the Hartsville and Palo Verde Nuclear Generating Stations; (2) the identification of incorrect connection of differential pressure gages in air clean up units furnished to Bellefonte Units 1 and 2; (3) the identification of defective Flanders Filters charcoal adsorber trays at Sequoyah Units 1 and 2; (4) the identification of separation of screens from charcoal ausorber frames at the Phipps Bend and Hartsville Nuclear Stations; and (5) the identification of inadequate fire protection system drains in standby gas treatment charcoal adsorbers furnished to the Phipps Bend and Hartsville Nuclear Stations.

Areas examined and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

During the inspection it was found that the implementation of your QA program failed to meet certain NRC requirements. The specific findings and references to the pertinent requirements are identified in the enclosures to this letter.

Please provide us within 30 days of the date of this letter a written statement containing, (1) a description of steps that have been or will be taken to correct these items, (2) a description of steps that have been or will be taken to prevent recurrence, and (3) the date your corrective actions and preventive measures were or will be completed. Consideration may be given to extending your response time for good cause shown.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's

OFFICE				IES	DØ-RIV	
	HRoberds:bb IBarnes		UPotapovs	JEGagliardo	Jacollins	
DATE	6/3/81	6/ 8/81	6/8/81	6/ 1/81	6/9/81	
NRC FORM	1 318 (10-80) N 3CM	VI 0240	OFFICIAI	RECORD CO	DPY	

B10B110572 B10610 PDR 0A999 EECMCWCT

## CTI - Nuclear

. .

Public Document Room. If this report contains any information that you believe to be exempt from disclosure under 10 CFR 9.5(a)(4), it is necessary that you (a) notify this office by telephone within 10 days from the date of this letter of your intention to file a request for withholding; and (b) submit within 25 days from the date of this letter a written application to this office to withhold such information. If your receipt of this letter has been delayed such that less than seven days are available for your review, please notify this office promptly so that a new due date may be established. Consistent with Section 2.790(b)(1), any such application must be accompanied by an affidavit executed by the owner of the information which identifies the document or part sought to be withheld, and which contains a full statement of the reasons on the basis which it is claimed that the information should be withheld from public disclosure. This section further requires the statement to address with specificity the considerations listed in 10 CFR 2.790(b)(4). The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified periods noted above, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely, "Original Signed by: U, POTAPOVS"

Uldis Potapovs, Chief Vendor Inspection Branch

Enclosure:

1. Notice of Nonconformance

2. Inspection Report No. 99900747/81-01

bcc: Chief, V&SPB, DR&RRI, HQS (Reinmuth) IE Files NRR:DPM:QAB Reg. Directors, I, II, III, V Central Files PDK HQS JEGagliardo, RIV ASME NBB&PVI

NRC FORM 318 (10-80) NRCM 0240 OFFIC!AL RECORD COPY									
			*********		******************				
	the second se	· · · · · · · · · · · · · · · · · · ·							