



Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

DYMB/LEK



July 13, 1981

DJS LTR #81-567

James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Reportable Occurrence Report #81-16/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

This revised report corrects a statement in the cause section, which indicated that the off-steam monitor was replaced with the on-steam monitor when the actual case is the reverse.

D. J. Scott Jr

D. J. Scott
 Station Superintendent
 Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 U.S. NRC, Document Mgt. Branch
 File/NRC

*FE22
 S
 1/1*

8108110622 810713
 PDR ADOCK 05000237
 S PDR

AUG 3 1981