PACIFIC GAS AND ELECTRIC COMPANY

July 21, 1981

ROBERT OHLBACH

CHARLES T. VAN DEUSEN PHILIPA CRANE, UR. HENRY J. LAPLANTE JOHN B. GIBSON ARTHUR L. HILLMAN, JR. CHARLES W. THISSELL DANIEL E. GIBSON JACK F. FALLIN, JR. JOSEPH I. KELLY ADDISTRAY GENERAL COUNSEL

P. O. BOX 7442 . TT BEAVE TREET, 31ST/1000R, SAN FRANCISCO, CALIFORNIA 94106 TELECOPIER (415) 543-7813 TELEPHONE (415) 781-421

Mr. Ge je Spencer, Director Division of Technical Inspection Regin V U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement 1990 N. California Boulevard Walnut Creek Plaza, Suite 202

> Re: Docket No. 50-275 Docket No. 50-323

Diablo Canyon Units 1 and 2

Dear Mr. Spencer:

Walnut Creek, CA 94596

This letter supplements our previous responses to IE Bulletin 79-02 by addressing the potential impact of reduced ultimate tensile values for one-inch diameter HILTI expansion anchors.

As indicated in our May 5, 1981 letter to you, we have reduced the allowable pullout loads on one-inch HILTI anchors to reflect the lower ultimate tensile loads provided by HILTI and to comply with the IE Bulletin 79-02 requirement for a safety factor of at least 4. The pullout allowables on page 8 of attachment II, in our letter to you dated December 3, 1980, were revised accordingly. This revision is shown in the attachment to this letter. The new values do not change our previous conclusions. Our review identified one pipe support with bolts which did not meet the required safety factor. This support has been modified to meet the required safety factor. Had this change not been made, the potential effect on safety would have been minimal since the support bults would have had a safety factor of 3.9 or only 2.5% below the required value.



Mr. George Spencer - 2 -July 21, 1981 The lower allowable loads for one-inch HILTI anchors have been used by PGandE since March 5, 1981, and are being applied to all new piping support designer and to the Diablo Canyon Unit 2 review for IE Bulletin 79-02. This assures that the required safety factors will be met in all cases. Very truly yours, Attachment CC: Service List

ATTACHMENT

Revised Allowable Loads

From: Teledyne Engineering Services

Technical Report TR-4121-2, Page 8

		100	4000	6000		
Diam.	E oed.	Pu/4	Vu/4	<u>Pu/4</u>	<u>Vu/4</u>	
1"	4-1/2 5 6 7 8 9	4000 4725 5860 5860 5860 5860 5860	6720 6720 6720 6720 8623 8623 8623	5125 5860 5860 5860 5860 5860 5860	8028 8028 8023 8028 9098 9098	
,1-1/4"	5-1/2" 6-1/2" 7-1/2" 8-1/2" 9-1/2" 10-1/2"	5750 6775 7775 8650 9450 15,225	8920 8920 8920 8920 8920 8920	7800 9125 10,500 11,100 11,100	11,298 11,298 11,798 11,774 11,774 12,399	

PHILLIPS WEDGE MIN. EMB.

	Catalog Values		Teledyne Values from Generic Program		Use These*	
Size	Pu/4	Vu/4	Pu/4	Vu/4	Pu/4	Vu/4
1/2" 5/8" 3/4" 7/8"	1475 1956 2875 2950	2100 3000 4250 6225	1313 2563 2375 3354	1750 3313 4438 4875	1313 1956 2375	1750 3000 4250
1" 1-1/4"	4075 10,150	8850 12,150	5958 7000	10,000	2950 4075 7000	4875 8850 11,250

^{*}Lowest Value

⁽a) Revised Values