## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street To or II

August 7, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT BFR0-50-260/81040

The enclosed report provides details concerning recirculation pump B which tripped while valving reactor water level switch LIS-3-56C into service. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

A. J. Green Director of Nuclear Power

Enclosure (3) cc (Enclosure): Director (3)

Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

AUG 1 2 1981 - 1

O. AUG 1 2 1981 - 1

O. AUG 1 2 1981 - 1

O. AUG 1 2 1981 - 1

8108130261 810807 PDR ADOCK 05000260 S PDR I E 2 2