

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

August 14, 1981

31 AUG 17 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-259/81042

The enclosed report provides details concerning the unit 1 250 volt  
main battery No. 1 which was removed from service in order to bypass  
a cracked cell. This report is submitted in accordance with  
Browns Ferry unit 1 Technical Specification 6.7.2.b.2.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Loper*  
H. J. Green  
Director of Nuclear Power



Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (4C)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

IE22  
S  
1/1

8108200141 810814  
PDR ADOCK 05000259  
S PDR