

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242


WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

August 24, 1981

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303


Re: McGuire Nuclear Station  
Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report R0-369/81-125. This report concerns T.S. 3.3.1, "As a minimum, the reactor trip system instrumentation channels and interlocks of Table 3.3-1 shall be operable..." This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

  
William O. Parker, Jr.

PBN/php  
Attachment

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavalee  
Nuclear Safety Analysis Center  
P. O. Box 10412  
Palo Alto, California 94303

Ms. M. J. Graham  
Resident Inspector-NRC  
McGuire Nuclear Station

IE22  
S  
1/1

8109080212 810824  
PDR ADOCK 05000369  
S PDR