

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A L J M F | 2 0 0 - 0 0 0 0 0 - 0 0 3 | 4 1 1 1 1 | 4 | 5

REPORT SOURCE L 6 | 0 5 0 0 0 3 6 | 4 7 | 0 8 0 1 8 1 | 3 | 0 8 3 1 8 1 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 | At 1825 on 8/1/81, the instrumentation loop associated with the refueling water storage

0 3 | tank level transmitter (LT-501) was declared inoperable when the level indicator

0 4 | (LI-4075A) failed high. Tech. Spec. 3.3.3.8, in part, requires the instrumentation loop

0 5 | to be operable. Tech. Spec. 3.3.3.8 action statement requirements were met. Health/

0 6 | safety of the public was not affected.

0 7 |

0 8 |

0 9 |

SYSTEM CODE I D 11 | CAUSE CODE C 12 | CAUSE SUBCODE Z 13 | COMPONENT CODE I N S T R U 14 | COMP. SUBCODE T 15 | VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 8 1 17 | SEQUENTIAL REPORT NO. 0 3 3 24 | OCCURRENCE CODE 0 3 28 | REPORT TYPE L 30 | REVISION NO. 0 32

ACTION TAKEN X 18 | FUTURE ACTION Z 19 | EFFECT ON PLANT Z 20 | SHUTDOWN METHOD Z 21 | HOURS 0 0 0 0 22 | ATTACHMENT SUBMITTED N 23 | NPRO-4 FORM SUB. N 24 | PRIME COMP. SUPPLIER N 25 | COMPONENT MANUFACTURER W 1 2 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The event was caused by moisture entering the transmitter junction box during a rainstorm.

1 1 | The junction box was dried and Instrumentation loop LT-501 was returned to service at

1 2 | 0510 on 8/2/81. The junction box has subsequently been sealed to prevent recurrence

1 3 | of this event.

1 4 |

FACILITY STATUS 1 29 | % POWER 1 0 29 | OTHER STATUS N/A 30 | METHOD OF DISCOVERY A 31 | DISCOVERY DESCRIPTION Operator Observation 32

ACTIVITY CONTENT Z 33 | RELEASED OF RELEASE Z 34 | AMOUNT OF ACTIVITY N/A 35 | LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 | TYPE Z 38 | DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 | DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 | DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 | DESCRIPTION N/A 45

8109070450 810831
 PDR ADDCK 05000364
 S PDR

NRC USE ONLY