

DYMB/LER

NRC-81-144

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305



September 1, 1981

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305
Operating License DPR-43
Reportable Occurrence LER 81-024/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 81-024/03L-0 is being submitted. Due to an administrative error, the reporting period of 30 days has been exceeded for this LER.

Very truly yours,

C. A. Schock for

E. R. Mathews
Senior Vice President
Power Supply & Engineering

jac

Attach.

- cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, DC 20555
- Dir, Office of Mgt Info & Program Control
US NRC, Washington, DC 20555
- Mr. W. Lavalley, NSAC
PO Box 10412, Palo Alto, CA 94303
- Mr. Robert Nelson, NRC Resident Inspector
RR #1, Box 999, Kewaunee, WI 54216

*IE 22
5/1*

8109100298 810901
PDR ADOCK 05000305
S PDR

SEP. 4 1981