## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Towe, fI

September 8, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - REPORTABLE OCCURRENCE REPORT SQR0-50-328/81104

The enclosed report provides details concerning three containment spray test line return isolation values to the refueling water storage tank being found open. This event required entry into limiting conditions for operation 3.6.2.1 and 3.0.3 and is reported under Sequoyah unit 2 Technical Specification 6.9.1.12.f. Attached to the LER is additional information in the form of a report prepared by a TVA investigation team.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

P.R. Walla

H. J. Green Director of Nuclear Power




1.18

Enclosures (3) cc (Enclosures): Director (3) Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

NRC Inspector, Sequoyah



IE27 511.