
Docket No. 50-344 Bulletin 81-02 RECEIVED



1991 SEP 10 AM 9 09

Bart D Withers Vice President

REGION 1

September 4, 1981

Trojan Nuclear Plant Docket 50-344 License NPF-1

Mr. R. H. Engelken, Director U. S. Nuclear Regulatory Commission Region V Walnut Creek Plaza, Suite 202 1990 N. California Blvd. Walnut Creek, CA 94596

Dear Mr. Engelken:

This is in response to IE Bulletin 81-02, Supplement 2, birtue st 18, 1981 concerning the failure of gate-type valves to close against differential pressure. No Westinghouse Electro-Mechanical Division valves as identified in this Bulletin Supplement are installed in any safety-related system or maintained as spares at the Trojan Nuclear Plant. No further response or corrective action as outlined in the Bulletin Supplement is warranted. Approximately twenty man-hours were expended in the investigation and preparation of this report.

Sincerely,

Vice President

Nuclear

c: Mr. Lynn Frank, Director State of Oregon Department of Energy

> Director, Office of Inspection and Enforcement U. S. Nuclear Regulator, Commission