

NOTICE OF VIOLATION

Sure Shot Perforators, Inc.

Docket: 30-15217  
License: 35-19013-01

As a result of the inspection conducted on August 12, 1981, and in accordance with the attached Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violations were identified:

1. License Condition 10 requires, in part, that licensed material be used at licensee's facilities at Highway 99 and 16, Drumright, Oklahoma.

Contrary to this requirement, the licensee was using material at his new facility located one-half mile west of Shamrock, Oklahoma, on Highway 16.

This is a Severity Level V violation (Supplement VII.E).

2. License Condition 18 requires, in part, that licensed activities be conducted in accordance with statements, representations, and procedures contained in the application dated April 20, 1979.

Contrary to this requirement, survey instrument calibration was not performed at six month intervals during the period December 1979 to August 1981.


This is a Severity Level V violation (Supplement VII.E).

Pursuant to the provisions of 10 CFR 2.201, Sure Shot Perforators, Inc., is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation. Consideration may be given to extending your response time for good cause shown.

The responses directed by this Notice are not subject to the clearance procedures of the office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

SEP 24 1981

Dated \_\_\_\_\_

  
Glen D. Brown, Chief  
Technical Inspection Branch