



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 22, 1981

D. L. ASWELL
Vice President-Power Production

W3K-81-0340
Q-3-A35.07
Q-3-A35.02.01

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Final Report of Potentially Significant Construction Deficiency
No. 48 "Flammability of Cable Pulling Compound"

Reference: Telecon - L. L. Bass (LP&L QA) to B. Hubacek (NRC) on July 20, 1981

Dear Mr. Seyfrit:



We have completed our evaluation of the reportability of the subject deficiency under 10CFR50.55(e) and have determined that it is not reportable. The results of our review are on file at the Waterford SES Unit No. 3 site and are available for your inspection.

Very truly yours,

D. L. Aswell

DLA/LLB/grf

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



8110060295 810922
PDR ADOCK 05000382
S PDR

IE 27
S 1/0

50.55(e) NHB
IE NQ's file copy