

TENNESSEE VALLEY AUTHORITY REGION II  
CHATTANOOGA, TENNESSEE 37401  
ATLANTA, GEORGIA

400 Chestnut Street Tower II

81 OCT 28 09:13  
October 26, 1981

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


BELLEFONTE NUCLEAR PLANT UNIT 2 - WELDING OF STRUCTURAL STEEL ANNULUS FLOOR  
FRAMING - NCR 1173 - SEVENTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector R. W. Wright on April 15, 1980, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated May 15, July 30, and November 7, 1980, and February 20, June 23, and July 28, 1981. Approximately 456 welds have been reinspected from the 566 weld samples selected per MIL-Standard 105D. TVA is continuing the reinspection of the remaining welds. We expect to submit our next written report by February 10, 1982.

If you have any questions concerning this matter, please get in touch with R. H. Shell at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IE27  
s  
110

8111030494 811026  
PDR ADDCK 05000439  
S PDR