

APPENDIX  
NOTICE OF VIOLATION

H&G Inspection Company, Inc.  
Houston, Texas

Docket: 30-29319/90-01  
License: 42-26838-01

During an NRC inspection conducted on January 10-11 and February 13-14, 1990, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1989) (Enforcement Policy), the violation is listed below:

License Condition 17 requires, in part, that the licensee conduct its program in accordance with statements, representations, and procedures contained in the letter dated July 22, 1986.

Section IV, Item 2.6 of the "Equipment Handling Procedure" enclosed with the letter requires, in part, that any deficiencies found during the equipment inspection be brought to the attention of the radiation safety officer immediately.

Contrary to the above, during the period August 24-31, 1988, a radiographer found a deficiency in the operation of the locking mechanism on a crank-out exposure device, but did not bring the deficiency to the attention of the radiation safety officer and continued to use the defective device.

This is a repeat violation.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, H&G Inspection Company, Inc., is hereby required to submit to this office, within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the reason for the violation if admitted, (2) the corrective steps which have been taken and the results achieved, (3) the corrective steps which will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas,  
this 23rd day of March 1990