

May 5, 1983

Log No. K83-689 File: RR2 (NP-33-83-20)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 83-016 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: April 7, 1983

Enclosed are three copies of Licensee Event Report 83-016 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Temp Munay

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station


TDM/ljk

Enclosures

cc: Mr. Richard DeYoung, Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Tom Peebles NRC Resident Inspector Encl: 1 copy



THE TOLEDO EDISON COMPANY

EDISON PLAZA 300 MADISON AVENUE

TOLEOO, OHIO 43652

MAY 9 1983

1833