



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

May 11, 1983

83 MAY 16 AIO: 12

REGION II  
STATE OF GEORGIA

JAMES P. McGAUGHY, JR.  
VICE PRESIDENT

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 2900  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Reactor Vessel Flange and Head  
Flange Temperature  
Surveillance Requirements  
Not Met  
LER 83-052/03 L-0  
AECM-83/0275

On April 11, 1983, while reviewing the vessel head installation work package, it was discovered that the head flange and vessel flange thermocouples had not been physically reinstalled during the insulation installation. The surveillance requirements of Technical Specification 4.4.6.1.4 were not met. The event is reported pursuant to Technical Specification 6.9.1.13.b.

Yours truly,

*J.P. McGaughey*  
for J. P. McGaughey

JPM:sap  
Attachment

- cc: Mr. J. B. Richard (w/a)
- Mr. R. B. McGehee (w/o)
- Mr. T. B. Conner (w/o)
- Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Document Control Desk (w/a)  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY

IE 22

8305200523 830511  
PDR ADOCK 05000416  
S PDR