

General Offices . Seldon Street, Berlin, Connecticut

P.O. BOX 270 HARTFORD, CONNECTICUT 06141-0270 (203) 666-6911

June 16, 1983

Docket No. 50-423 B10818

Dr. Thomas E. Murley Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Reference:

(1) W. G. Counsil letter to R. C. Haynes, Millstone Nuclear Power Station, Unit No. 3, Reporting of Potential Significant Deficiencies in Design and Construction: Cracks Related to Embedments ii. the Containment Crane Wall (SD-29), dated December 7, 1983.

Gentlemen:

Millstone Nuclear Power Station, Unit No. 3, Reporting of Potential Significant Deficiencies in Design and Construction: Cracks Related to Embedments in the Containment Crane Wall (SD-29)

In Reference (1), Northeast Nuclear Energy Company (NNECO) reported a potential significant deficiency as required by 10 CFR 50.5%(e), concerning cracks in the containment crane wall near embedments.

We are unable at this time to provide a final report describing the corrective and preventive measures to be taken, because our evaluation has not been completed. We will provide you with an update of our progress on this matter on or before September 1, 1983.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

W. G. Counsil

Senior Vice President

8307010148 830616 PDR ADOCK 05000423 PDR

JE10