

DMB

June 28, 1983

Docket No. 50-315  
Docket No. 50-316

American Electric Power Service  
Corporation  
Indiana and Michigan Electric Company  
ATTN: Mr. John E. Dolan  
Vice Chairman  
Engineering  
2 Broadway  
New York, NY 10004

Gentlemen:

This refers to the routine safety inspection conducted by Mr. L. J. Hueter of this office on April 27-29 and May 3-6, 1983, of activities at Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Licenses No. DPR-58 and No. DPR-74, and to the discussion of our findings with Mr. W. G. Smith and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

We are concerned that during the inspection you did not have documentation available to demonstrate conformance to the clarifications for the post-TMI items specified in NUREG-0737 and the NRC Order dated March 14, 1983. We consider such documentation essential for you to ensure conformance to NUREG-0737 and the NRC Order. We will examine this matter further during future inspections.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure(s) will be placed in the NRC Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1). If we do not hear from you in this regard within the specified periods noted above, a copy of this letter, the enclosure(s), and your response to this letter will be placed in the Public Document Room.

American Electric Power Service  
Corporation


2

June 28, 1983

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



C. J. Paperiello, Chief  
Emergency Preparedness and  
Radiological Safety Branch

Enclosures:

1. Appendix, Notice  
of Violation
2. Inspection Reports  
No. 50-315/83-08(DRMSP);  
No. 50-316/83-09(DRMSP)

cc w/encls:

W. G. Smith, Jr., Plant Manager  
DMB/Document Control Desk (RIDS)  
Resident Inspector, RIII  
Ronald Callen, Michigan  
Public Service Commission  
EIS Coordinator, USEPA  
Region 5 Office

RIII

*LDH*  
Hueter/bl  
06/20/83

RIII

*Greger*  
Greger

RIII

~~X~~  
Arlson

RIII

*Boyd*  
Boyd  
6/27/83

RI. I

*Paperiello*  
Paperiello  
6/27/83