

**EXXON NUCLEAR COMPANY, Inc.**

2701 Hays Ridge Road

P. O. Box 138, Richmond, Washington 22357

Phone: (509) 375-8100 Telex: 15-2878

July 13, 1983

Mr. James V. Zimmerman, Assistant Director  
Export/Import and International Safeguards  
Office of International Affairs  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Reference: Hardware Export License XCOM0369

Dear Mr. Zimmerman:

Attached is an application for an export license for repair parts to be sent to the Barsebaeck I reactor in Sweden. These repair parts consist of tie plate assemblies and their associated hardware. The cost of a tie plate assembly is estimated at approximately \$400.

It is requested that the license be issued on an emergency basis to allow the shipment of 10 tie plate assemblies as soon as possible. It is further requested that an exemption be granted to the 15-day waiting requirement for the current shipment.

Recent information from reactor fuel inspections indicates that this repair procedure will continue through the year 1986. Therefore, it is requested that the license be issued to cover the replacement of these assemblies--approximately 40 in all or a \$40,000 value.

It would be greatly appreciated if the License Number could be telephoned to me as soon as the license is signed.

If you have any questions regarding the application or if you need additional information, please contact me (509) 375-3674.

Sincerely,

*G. R. Kiel*

G. R. Kiel  
Licensing Specialist

/lr

RAF FAX  
PAGE  
ATTN

NO. 202  
OF 2

*E. Elaine Hamby*