

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | M | D | C | C | N | 1 | 0 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5

CONT

01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 7 | 7 | 0 | 6 | 1 | 0 | 8 | 3 | 9 | 0 | 7 | 0 | 8 | 8 | 3 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 | During normal power operation at 1130, ESFAS Channel ZG steam generator
03 | level was found to be tripped (T.S. 3.3.2.1.b). Repairs to the channel
04 | were completed and the channel was returned to service at 1430. During
05 | this event all remaining channels remained operable.
06 | Similar events: 50-317/83-17; 50-318/82-02.

09 | I | B | E | G | I | N | S | T | R | U | Y | Z | 8 | 3 | 0 | 3 | 5 | 0 | 3 | L | 0 | C | X | Z | Z | 0 | 0 | 0 | 0 | N | Y | N | V | 1 | 3 | 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 | The cause of the tripped ESFAS channel was found to be a failed Vitro
11 | isolator module (N#04341.26023 VL-C-23929). The module was replaced
12 | with a spare and returned to Vitro for repair and root cause analysis.
13 | An update will be submitted when the failure analysis is returned from
14 | the vendor.

15 | E | 1 | 0 | 0 | N/A | A | Operator Observation

16 | Z | Z | N/A | N/A

17 | 0 | 0 | 0 | Z | N/A

18 | 0 | 0 | 0 | N/A

19 | Z | N/A

20 | N | N/A

8307210285 830708 PDR ADOCK 05000317 S PDR

JE22

NAME OF PREPARED BY R. J. Porter/L. F. Basso PHONE: 301-269-4747/4933

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT  
CALVERT CLIFFS NUCLEAR POWER PLANT  
LUSBY, MARYLAND 20657

July 8, 1983

Dr. Thomas Murley  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region 1  
631 Park Avenue  
King of Prussia, PA 19406


Docket No. 50-317  
License No. DPR 53

Dear Dr. Murley:

Attached is LER 83-35/3L, as required by Technical Specification 6.9.

If you have any questions regarding this report, we would be pleased to discuss them with you.

Very truly yours,



*for* L. B. Russell  
Plant Superintendent

LBR:LFB:bsb

cc: Director, Office of Management Information  
and Program Control  
Messrs: A. E. Lundvall, Jr.  
J. A. Tiernan

// IER