


**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 29, 1983

W3I83-0290  
Q-3-A35.07.68

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 68  
"Spurious ESFAS Actuation"  
Fifth Interim Report

REFERENCE: LP&L Letter W3I83-0226 dated June 22, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than August 26, 1983.

At the present time, the corrective action associated with this deficiency has been completed and the supporting documentation is currently under review. A Final Report will therefore be submitted to the USNRC by October 28, 1983.

Very truly yours,

F. J. Drummond  
Manager, Engineering & Technical Services

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

3) Mr. E. L. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

4) Mr. W. M. Stevenson

8309080038 830829  
PDR ADOCK 05000382  
S PDR

IE-27

1/0