



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

October 13, 1978

2-108-6

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence
Report Nos. 50-368/78-4,
50-368/78-5, 50-368/78-6
and 50-368/78-7
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached four (4) Reportable Occurrence Reports concerning: the loss of two independent off site power sources (78-4); AC Electrical buses not operable (78-5); the RWT level being less than the minimum required (78-6); and the Chloride concentration being out of limits (78-7). As committed, we have also enclosed a description of the sequence of events that transpired on September 16, 1978, associated with the above occurrences.

Very truly yours,

Daniel H. Williams

Daniel H. Williams
Manager, Licensing

DHW:REI:mh

Attachments

781103 0145 (5)

A002
5/11