




**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

September 30, 1982

L. V. MAURIN
Vice President
Nuclear Operations

W3I82-0052
Q-3-A35.07.48



Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 2
Docket No. 50-382
Significant Construction Deficiency Report No. 48
"Design Application of Break Flanges at Elevated Temperatures"
Second Interim Report

REFERENCE: LP&L Letter W3K-82-0175 dated March 26, 1982

Dear Mr. Collins:

The corrective action as described in the reference above has not yet been completed. A final report will, therefore, not be submitted until January 17, 1983.

Very truly yours,

L. V. Maurin

LVM/MAL:keh

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27

8210130564 820930
PDR ADOCK 05000382
S PDR