

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | J | S | G | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 1 | 7 | 0 | 8 | 1 | 4 | 8 | 2 | 8 | 0 | 8 | 1 | 8 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | On August 14, 1982, a 1 GPM service water leak was discovered on No. 22 Containment Fan
03 | Coil Unit (CFCU). No. 25 CFCU was inoperable at the time, and Action Statement
04 | 3.6.2.3.a was in effect. With an additional CFCU inoperable, Action Statement 3.6.2.3.b
05 | was entered. The unit was immediately isolated. No. 25 CFCU was repaired later that
06 | day, and Action Statement 3.6.2.3.b was terminated. (see LER 82-074) On August 15, a
07 | similar leak was discovered on No. 24 CFCU; this unit is in the same group as No. 22,
08 | hence, Action Statement 3.6.2.3.a still applied. The events constituted degradation of

9 containment in accordance with Technical Specification 6.9.1.8.c.
09 | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP. SUBCODE | VALVE SUBCODE
7 8 9 10 11 12 13 18 19 20

17 | LER NO REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO. | OCCURRENCE CODE | REPORT TYPE | REVISION NO.
21 22 23 24 26 27 28 29 30 31 32
18 | ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRO-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | No. 22 CFCU was repaired by blanking the flanges in the service water piping to the
11 | coil. The leak on No. 24 CFCU was repaired with Belzona metal filler. With both
12 | units operable, Action Statement 3.6.2.3.a was terminated. New design coils will be
13 | installed during the next refueling.
14 | (82-074, 82-073, 82-070, 82-040, 82-028)

15 | FACILITY STATUS | % POWER | OTHER STATUS (30) | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 44 45 46 80

16 | ACTIVITY CONTENT | RELEASED OF RELEASE | AMOUNT OF ACTIVITY (35) | LOCATION OF RELEASE (36)
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES | NUMBER | TYPE | DESCRIPTION (39)
7 8 9 10 11 12 13 80

18 | PERSONNEL INJURIES | NUMBER | DESCRIPTION (41)
7 8 9 10 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY | TYPE | DESCRIPTION (43)
7 8 9 10 80

20 | PUBLICITY | ISSUED DESCRIPTION (45) | NAME OF PREPARER | PHONE
7 8 9 10 80
R. Frahm
609/935-6000 Ext 3078
NRC USE ONLY