NRC FORM 366 (12-81)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)		
0 1 S C V C S 1 2 0 7 8 9 LICENSEE CODE 14 15	0 0 - 0 0 0 0 0 - 0 0 3 4 1	0 0 0 0 4 57 CAT 58 6
CON'T  0 1  REPORT L 6 0 5 0  7 6 61 DC	0 U 0 3 9 5 7 0 9 2 9 8 2 6	B 1 0 2 6 8 2 9
EVENT DESCRIPTION AND PROBAB		
	initial plant startup and having rece	
0 3   Technical Specificat	ion 4.7.5 requires Service Water Pond	l level verification
0 4 at least once every	24 hours. These readings were omitted	ed from 9/22/82 to
0 5 9/29/82. There were	no adverse consequences since the pl	lant had no inventory
0 6 of decay heat. Also	, it was verified that the pond had t	not dropped below the
0 7 Technical Specificat	ion minimum level.	
0 8 1		
7 6 SYSTEM CAU		OMP. VALVE CODE SUBCODE
0 9 Z Z 110 A	1011010101010101	Z (5) Z (6)
17 REPORT   8 2	9 m m m m m m m m m m m m m m m m m m m	PORT REVISION NO.
ACTION PUTURE EFFECT ON PLANT  X (18) G (19) Z (20)	SHUTDOWN   HOURS   22 ATTA CHMENT   NPRD-4   SUBMITTED   FORM SUB   22   21   0   0   0   Y   23   N   (	PRIME COMP. SUPPLIER  Z Z 25 Z 9 9 9 9 47
CAUSE DESCRIPTION AND CORRECT	CTIVE ACTIONS (27)	n process the Service I
The state of the s	re recently revised. In the revision ry was omitted by personnel error.	
to include this surv	reillance. Also, the Logs were review	wed to ensure that all
13   required Tech. Spec.	surveillances assigned to be covered	d on logs were infact
included. No additi	onal problems were discovered.	
1 5 B 28 0 0 0 0 29	N/A 30 NRC Resident	
ACTIVITY CONTENT AMOUNT O	N/A N/A LOCATIO	ON OF RELEASE (36)
7 8 9 10 11	44 45	60
1 7 0 0 0 37 Z 38	N/A	60
PERSONNEL INJURIES NUMBER DESCRIPTION (41)	N/A	
7 8 9 11 12		80
TYPE DESCRIPTION (43)	N/A B211040105 B21026 PDR ADDCK 05000395 PDR	80
ISSUED DESCRIPTION (45)	S N/A	NRC USE ONLY
7 8 9 10	N/A	68 69 80 6 (803) 345-5209
NAME OF PREPARER	Curtis Fields PHON	(803) 345-5209