0.111

Unit 2.

125	CONTROL BLOCK:
	The state of the s
0 1	T N S N P 2 3 0 0 - 10 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 1 3 4 1 57 CAT SE
O I	SOURCE L 6 0 5 10 10 0 13 12 18 7 10 19 12 17 18 12 18 11 10 12 15 18 12 9
, 1,	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	At 0440 on 09/27/82, unit 2 in mode 1, containment isolation valve 2-FCV-30-17,
0 3	lower compartment purge air supply valve would not open during the performance of
0 4	SI-166.1. This event required entry into the action statement of LCO 3.6.3.
0 5	There was no effect on public health or safety. Previous occurrences - none.
0 6	The same of the sa
0 7	
0 8	
7 . 8	SYSTEM CAUSE CAUSE COMPONENT CODE COMP. VALVE CODE SUBCODE
7 8	SD 11 E 12 A 13 V A L V 10 P 14 F 15 Z 16
	LERIAD EVENT YEAR REPORT NO. LODE TYPE NO.
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD 4 PRIME COMP. COMPONENT METHOD HOURS 22 SUBMITTED FORM SUB, SUPPLIER MANUFACTURER
4889	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
10	Investigation revealed an open coil in the valve operator. The failure of the
III	coil is due to normal end of life. The coil was replaced, the valve was tested
2000	
1 2	and returned to service at 0630 on 09/27/82. No additional corrective action is
13	planned.
1 4	9
1 5	E 28 1 0 0 29 NA NETHOD OF DISCOVERY DESCRIPTION 32
	CTIVITY CONTENT 12 13 44 45 46 80 LOCATION OF RELEASE 36
1 6	Z (33) Z (34) NA
	NUMBER TYPE DESCRIPTION (30)
7 8	PERSONNEL INJURIES 80
18	NUMBER DESCRIPTION (41) NA
7 8	2 11 17 LOSS OF OR DAMAGE TO FACILITY 43 8211040130 821025
, 9	Z (42) NA PDR ADGCK 05000320
	PUBLICITY ISSUED DESCRIPTION 45
, 8	Name of Preparer: W. D. Romine /M. R. Harding Phone: (615) 751-0349