| (7.77)        | LICENSEE EVENT REPORT  Attachment to AECM-82/486 Page 1 of 1   |
|---------------|--|
|               | CONTROL BLOCK:             (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)   |
| 0 1           | M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAY 58  |
| CON'T 0 1 7 8 | SOURCE L 60 5 0 0 0 4 1 6 7 0 9 1 6 8 2 8 1 0 1 8 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  |
| 0 2           | While performing work under Design Change Package 82-4145 issued 9 / 4/82 for completion   |
| 0 3           | of the original construction of the heat tracing portion of the Drywell Monitoring   |
| 0 4           | System, three secondary containment penetrations were opened for cable routing. The  |
| 0 5           | event is being reported pursuant to T.S.6.9.1.13.b. There was no effect to the health  |
| 0 6           | and safety of the public or a threat to plant safety.  |
| 0 7           |  |
| 0 8 7 8       | 9 SYSTEM CAUSE CAUSE COMP. VALVE   |
| 0 9 8         | CODE SUBCODE S |
|               | 17 REPORT NUMBER 21 23 24 26 23 28 29 30 30 31 32  |
|               | ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z  |
| 1 0           | This event was a planned maintenance activity. Secondary containment integrity was   |
| 111           | not required at the time of the maintenance activity. The penetrations were sealed on  |
| 1 2           | 9/18/82. An hourly fire watch was established during the interim pursuant to   |
| 1 3           | T.S.3.7.7. This is intended as a final report.   |
| 1 4           | 80   |
| 1 5           | FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32  |
|               | ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA NA NA NA NA NA  |
| 1 7           | PERSONNEL EXPOSURES NUMBER 17YPE 0 0 0 37 Z 38 DESCRIPTION 39 NA NA B0   |
| 1 8           | 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41) 9 0 0 0 40 NA  NA  NA   |
| 19            | LOSS OF DR DAMAGE TO FACILITY 43  TYPE DESCRIPTION NA  NA  |
| 2 0           | PUBLICITY   SSUED   DESCRIPTION (45)   B211040445   B21025   PDR   ADDCK   O5000416   PDR   68   69   80   5   |
|               | Original Signed by Ron Byrd  |