



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

November 12, 1982

50-266
301

Mr. Peter Anderson
Wisconsin's Environmental Decade
114 North Carroll Street
Suite 208
Madison, Wisconsin 53703

Dear Mr. Anderson:

In accordance with my letter to you dated June 17, 1982, I am enclosing the following:

- (1) "Summary of September 9, 1982 Meeting - San Onofre Nuclear Generating Station, Unit No. 1" dated September 23, 1982
- (2) Sections II, IV and V, Tables A-1, A-2, B-1 and B-4, Appendices D and F of the "Steam Generator Inspection Program, Return to Power Report, San Onofre, Nuclear Generating Station, Unit 1, September, 1982" (The other sections of the report do not address steam generator tubes and/or repair methods, including sleeving).

Also enclosed is the November 8, 1982 Daily Highlight from Point Beach, Unit 1, which concerns loose parts found in the secondary side of the steam generators. This was the subject of the letter from counsel for the Licensee to the Board dated November 9, 1982.

Sincerely,

Richard G. Bachmann
Counsel for NRC Staff

Enclosures: as stated

cc w/enclosures:

P. Bloch
H. Paxton
J. Kline
B. Churchill

cc w/o enclosures:

Remainder of Service List

ORIGINAL
Certified By DSOJ
CB