## LICENSEE EVENT REPORT

	LIGENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 2 7 2 7 1 1 0 4 8 2 8 1 1 1 1 0 8 2 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During routine surveillance testing from October 29 to November 11, 1982, the sixteen
0 3	1000 kip steam generator snubbers were found to be out of specification on the bleed
0 4	test required by the Technic Specifications. All units satisfactorily passed the
0 5	acceleration test. Core coo ing is being provided by the Residual Heat Removal System
0 6	and operability of the steam generators is not required. Due to the general nature of
0 7	the problem, the incident possibly involved the malfunction of components which could
08	prevent the fulfillment of the functional requirements of a safety system.
0 9	SYSTEM CAUSE CAUSE SUBCODE SUSCODE SUBCODE SUBCODE SUSCODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE SUS
	TO LER RO EVENT YEAR SEQUENTIAL REPORT NO.  LER RO EVENT YEAR SEQUENTIAL REPORT NO.  OCCURRENCE REPORT TYPE  NO.  O B 1  O D 1  T O D  O D D D  O D D  O D D  O D D  O D D  O D D  O D D  O D D  O D
	ACTION FUTURE TAKEN ACTION ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER SUPPLIER SUPPLIER SUPPLIER WANUFACTURER WANUFAC
10	An engineering evaluation is in progress to determine the cause of the incident, the
111	impact of the snubber inoperability, and appropriate corrective action. A Supplemental
1 2	Report will be submitted upon final resolution of the problem.
1 3	
14	
7 8	PACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Surveillance Testing
	PACTIVITY CONTENT 12 13 44 45 46 AG ACTIVITY CONTENT AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A N/A
7 8	9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  0 0 0 37 Z 38 N/A
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 B	0 0 0 40 N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
7 8	9 10 PUBLICITY 15SUED DESCRIPTION 45 PDR ADDCK 05000272 NRC USE ONLY PDR ADDCK 05000272 PDR
7 8	9 10 68 69 80 5 R. Frahm 609/935-6000 Ext 3078 9
	NAME OF PREPARER PHONE