



Commonwealth Edison

Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-82-504

November 5, 1982

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137


Reference: Quad-Cities Nuclear Power Station
Docket Number 50-254, DPR-29, Unit One
Appendix A, Sections 3.2.F.3 and 3.2.F.2

Enclosed please find Reportable Occurrence Report Number RO 82-34/03L-1 for Quad-Cities Nuclear Power Station. Only coding changes to the LER form have been made. Items 11 (Cause Code) and 12 (Cause Subcode) now classify the fuel pool radiation monitor instrument drift as an "Equipment Failure" of an "Instrument".

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.2.a; an engineered safety setting found less conservative than those specified by Technical Specifications which does not prevent the fulfillment of the functional requirements of the associated system.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION


N. J. Kalivianakis
Station Superintendent

NJK:HGL/bb

Encl:

cc T. J. Rausch
N. Chrissotimos
INPO Records Center

NOV 22 1982

8211300240 821105
PDR ADOCK 05000254
S PDR

IE 22