

# SAFEGUARDS INFORMATION

## U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

Report Nos. 50-361/82-37, 50-362/82-25 (IE-V-530)

Docket Nos. 50-361, 50-362

License Nos. NPF-10, None

Licensee: Southern California Edison Company  
P. O. Box 800  
2244 Walnut Grove Avenue  
Rosemead, California 91770

Facility Name: San Onofre Nuclear Generating Station, Units 2 & 3

Inspection at: Camp Pendleton, California

Inspection Conducted: September 27, 1982 through October 5, 1982

Date of Last Physical Security Inspection Visit: None

Type of Inspection: Announced, Preoperational, Physical Security

Inspectors: M. D. Schuster

M. D. Schuster, Chief, Physical Security Section  
and Inspection Team Leader

11/9/82

Date Signed

Wayne P. Mortensen

W. P. Mortensen, Physical Security Inspector

11/9/82

Date Signed

for M. D. Schuster

D. W. Schaefer, Physical Security Inspector

11/9/82

Date Signed

for M. D. Schuster

N. E. Ervin, Physical Security Inspector

11/9/82

Date Signed

Arthur D. McQueen

A. D. McQueen, Physical Security Inspector

11/9/82

Date Signed

Approved by: L. R. Norderhaug

L. R. Norderhaug, Chief, Safeguards Branch

11/9/82

Date Signed

### Inspection Summary

Areas Inspected: Security Plan; Security Organization-Management; Security Organization-Personnel; Security Organization-Response; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers - Protected Area; Physical Barriers - Vital Areas; Security System Power Supply;

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION.  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED.

## SAFEGUARDS INFORMATION

8211300361 821123  
PDR ADOCK 05000361  
PDR

Lighting; Assessment Aids; Access Control - Personnel; Access Control - Packages; Access Control - Vehicles; Detection Aids - Protected Area; Detection Aids - Vital Areas; Alarm Stations; Communications; and Independent Effort.

The inspection involved 345 hours on site by the inspection team. The inspection was begun during regular hours; of the total on-site inspection hours, 95 were accomplished during off-shift periods.

Findings: The licensee was found to be in compliance with their operating license requirements, within the areas inspected, except for the following three items:

1. Failure to search all personnel prior to protected area access (Severity Level IV).
2. Failure to search personnel in conformance with approved security plan (Severity Level IV).
3. Unsecure vital area portal (Severity Level IV).