



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

November 24, 1982

RECEIVED
NRC

NOV 26 AM 10 32

REGION V 118

R H ENGELKEN, REGIONAL ADMINISTRATOR
REGION V OFFICE OF INSPECTION AND ENFORCEMENT
U S NUCLEAR REGULATORY COMMISSION
1450 MARIA LANE SUITE 210
WALNUT CREEK CA 94596

DOCKET NO. 50-312
LICENSE NO. DPR-54
LICENSEE EVENT REPORT NO. 82-29

In accordance with Rancho Seco Nuclear Generating Station Technical Specifications, section 6.9.4.2.C, and Regulatory Guide 1.16, section C.2.b(3), the Sacramento Municipal Utility District hereby submits the following thirty-day report of Licensee Event Report No. 82-29.

On October 26, 1982, the District's Quality Assurance Department reported that a surveillance requirement was not addressed by procedure. Table 4.1-1 of Technical Specifications, item 48a, requires a monthly test of the Auxiliary Feedwater Start Circuit from the Phase Imbalance/Underpower RCP portion. Item 48b concerning the Low Main Feedwater Pressure portion does not require a monthly test, per the Technical Specifications. However, a surveillance was written and has been performed for item 48b, while no procedure was prepared for item 48a. This situation resulted from an apparent transposition of the requirements for items 48a and 48b. The District never intended to test the Phase Imbalance/Underpower portion of the AFW Start Circuit, since this test is extremely difficult to perform without tripping the pumps and, thus, causing a reactor trip. The District has committed to testing the start circuit for the AFW, but had intended that the Phase Imbalance/Underpower portion be tested/calibrated with the reactor shutdown. The monthly test was intended to address the Low Main Feedwater Pressure, which test was in fact conducted on a monthly basis.

As a corrective action, the District intends to request amendment of our Technical Specification to change the monthly requirement to item 48b


8212030084 821124
PDR ADOCK 05000312
S PDR

IF22

November 24, 1982

and to delete the requirement in 48a.

There were no effects on plant or public safety from this event.



John J. Mattimoe
General Manager

cc: DCD, Washington
INPO

