

JAN 3 1983

Docket Nos. 50-508
50-509

Washington Public Power Supply System
P. O. Box 968
3000 George Washington Way
Richland, Washington 99352

Attention: Mr. R. L. Ferguson
Managing Director

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP) for Washington Nuclear Project Nos. 3 & 5 and WPPSS Letter G03-82-1256 dated December 6, 1982.

This refers to the SALP for Washington Nuclear Project Nos. 3 & 5 conducted by this office for the period July 1, 1981 through July 31, 1982 and discussed with your staff at a meeting on November 4, 1982. The list of attendees is attached as Enclosure 1. The NRC SALP Report is attached as Enclosure 2. Washington Public Power Supply System letter G03-82-1256 dated December 6, 1982, which we requested in our letter dated October 27, 1982, provided licensee commitments for performance improvements. These letters are attached as Enclosures 3 and 4. Enclosure 5 is a copy of G03-82-1254 dated December 6, 1982, a supplementary response addressing Supply System management involvement and design control activities that was referenced in Enclosure 3.

Overall, your performance of licensed activities was found to be acceptable. Weaknesses were identified in Section IV of the SALP Report, primarily related to Supply System management involvement and onsite design control. During the meeting of November 4, 1982, we discussed our assessment of your performance in these areas. We have reviewed your letters of December 6, 1982 and determined that your actions to improve performance in the areas needing attention are responsive.

We consider that our meeting was beneficial and improved mutual understanding of your activities and our regulatory program. Based on your comments during the meeting and your December 6, letters, we have found that our assessment of "Soils and Foundation" should be rerated to Category 2 and is herein so noted. We have found that no other changes to our assessment are necessary.

8301070287 830103
PDR ADOCK 05000508
G PDR

1E01

OFFICE	RV/jk	JMS	BMS for	ENG	FA		
SURNAME	DODDS	STERNBERG	CREWS	ENGELKEN	FAULKENBERRY		
DATE	12/30/82	12/3/82	12/3/82	1/12/3/82	1/12/3/82		

OFFICIAL RECORD COPY

JAN 3 1983

In accordance with 10 CFR 2.790(a), a copy of this letter and its enclosures will be placed in the NRC Public Document Room. No reply to this letter is required. Your actions in response to the NRC Systematic Assessment of Licensee Performance will be reviewed during future inspections of your licensed activities.

Your cooperation is appreciated.

Sincerely,

Original signed by
R. H. Engelken

R. H. Engelken
Regional Administrator

Enclosures:
As stated

cc w/o enclosures:
R. B. Glasscock, Quality Assurance Director, WPPSS
R. S. Leddick, Program Director, WNP-3/5
D. E. Dobson, Project Manager, WNP-3/5

bcc: RSB/Document Control Desk (RIDS)

Distributed by RV:
State of WA (Lewis)
Resident Inspector (Albert)
Engelken (ltr)



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V
1450 MARIA LANE, SUITE 260
WALNUT CREEK, CALIFORNIA 94596

January 3, 1983

Docket Nos. 50-508
50-509

Washington Public Power Supply System
P. O. Box 968
3000 George Washington Way
Richland, Washington 99352

Attention: Mr. R. L. Ferguson
Managing Director

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP) for Washington Nuclear Project Nos. 3 & 5 and WPPSS Letter G03-82-1256 dated December 6, 1982.

This refers to the SALP for Washington Nuclear Project Nos. 3 & 5 conducted by this office for the period July 1, 1981 through July 31, 1982 and discussed with your staff at a meeting on November 4, 1982. The list of attendees is attached as Enclosure 1. The NRC SALP Report is attached as Enclosure 2. Washington Public Power Supply System letter G03-82-1256 dated December 6, 1982, which we requested in our letter dated October 27, 1982, provided licensee commitments for performance improvements. These letters are attached as Enclosures 3 and 4. Enclosure 5 is a copy of G03-82-1254 dated December 6, 1982, a supplementary response addressing Supply System management involvement and design control activities that was referenced in Enclosure 3.

Overall, your performance of licensed activities was found to be acceptable. Weaknesses were identified in Section IV of the SALP Report, primarily related to Supply System management involvement and onsite design control. During the meeting of November 4, 1982, we discussed our assessment of your performance in these areas. We have reviewed your letters of December 6, 1982 and determined that your actions to improve performance in the areas needing attention are responsive.


We consider that our meeting was beneficial and improved mutual understanding of your activities and our regulatory program. Based on your comments during the meeting and your December 6, letters, we have found that our assessment of "Soils and Foundation" should be rerated to Category 2 and is herein so noted. We have found that no other changes to our assessment are necessary.

January 3, 1983

In accordance with 10 CFR 2.790(a), a copy of this letter and its enclosures will be placed in the NRC Public Document Room. No reply to this letter is required. Your actions in response to the NRC Systematic Assessment of Licensee Performance will be reviewed during future inspections of your licensed activities.

Your cooperation is appreciated.

Sincerely,



R. H. Engelken
Regional Administrator

Enclosures:
As stated

cc w/o enclosures:
R. B. Glasscock, Quality Assurance Director, WPPSS
R. S. Leddick, Program Director, WNP-3/5
D. E. Dobson, Project Manager, WNP-3/5

ATTENDEES

Nuclear Regulatory Commission

B. H. Faulkenberry, Deputy Regional Administrator
D. M. Sternberg, Chief, Reactor Project Branch No. 1
R. T. Dodds, Chief, Reactor Project Section No. 1
W. G. Albert, Senior Resident Inspector
D. P. Haist, Reactor Inspector
R. W. Hernan, Licensing Project Manager

Washington Public Power Supply System

D. Mazur, Director of Operations
R. S. Leddick, WNP-3 Program Director
D. E. Dobson, WNP-3 Project Manager
O. E. Tropp, WNP-3 Project Quality Assurance
J. Puzauskas, WNP-3 Quality Assurance Supervisor
R. B. Glasscock, Director, Licensing and Assurance
L. J. Garvin, Manager, Construction Quality Assurance
G. D. Bouchey, Manager, Nuclear Safety and Regulatory Programs
A. D. Kohler, Director, Special Projects
D. L. Renberger, Deputy Director, Technology

Energy Facility Site Evaluation Council (Washington State)

G. H. Hansen, Senior Engineer

Bonneville Power Administration

D. Smithpofor, Project Engineer