

APPENDIX A

NOTICE OF VIOLATION

Kansas Gas and Electric Company

Docket: STN 50-482/82-17
License: CPPR-147

Based on the results of an NRC inspection conducted during the period of October 18-22, 1982, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987, dated March 9, 1982, the following violation was identified:

Failure to Provide Control of the Disassembly of Quality Accepted Pipe Supports

10 CFR Part 50, Appendix B, Criterion V, requires that activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings.

Contrary to the above, on October 21, 1982, the NRC inspector found quality accepted hanger #AE04-HC01/242 disassembled. Upon further review of the Daniel International Construction (DIC) procedures on safety-related pipe supports by the NRC inspector, it was found that there is no approved procedure to control the disassembly of quality accepted pipe supports by craft. It was also found that QC has no means of knowing when to reinspect these quality accepted supports after the supports have been reassembled.

This is a Severity Level IV Violation (Supplement II). (482/8217-01)

Pursuant to the provisions of 10 CFR 2.201, Kansas Gas and Electric Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: Novmeber 24, 1982