

January 14, 1983

DJS Ltr. #83-47

James G. Keppler, Regional Administrator Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Reportable Occurrence Report #83-02/01T-0, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(c), abnormal degradation discovered in fuel cladding, reactor coolant pressure boundary, or primary containment.

Station Superintendent Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement Director of Management Information & Program Control U.S. NRC, Document Management Branch File/NRC

JAN 24 1983 (LE 22)