




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

January 24, 1983



L. V. MAURIN
Vice President
Nuclear Operations

W3I83-0017
Q-3-A35.07.42
Q-3-A35.07.48

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Reopening of Significant Construction Deficiencies 42 and 48

Dear Mr. Collins,

As a result of a NRC site review of SCD files for which final reports have been submitted by LP&L, it has been determined that the final reports submitted for SCD's 42 and 48 do not adequately describe the scope of the corrective action performed. The Nonconformance Reports (NCR's) used to identify the problem and track the corrective action have been reopened. Upon disposition of these NCR's, LP&L will resubmit final reports for SCD's 42 and 48. It is anticipated that final reports on these SCD's will be transmitted to the NRC by February 14, 1983.

If you have any questions, please advise.

L. V. Maurin
L. V. Maurin

LVM/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) W. M. Stevenson

IF 27