



Nebraska Public Power District

COOPER NUCLEAR STATION
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321
TELEPHONE (402) 825-3811

DN: 50-298/
81-06

LQA8100062

June 9, 1981

Mr. W. C. Seidle, Chief
Engineering Inspection Branch
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 10
Arlington, Texas 76011

Subject: NPPD Response to IE Inspection Report No. 50-298/81-06

Dear Mr. Seidle:

This letter is written in response to your letter dated May 14, 1981, and the subsequent inspection report number 50-298/81-06.

Statement of Violation

Failure to Follow Procedures

10 CFR Part 50, Appendix B, Criterion V states that activities affecting quality shall be prescribed by documented instructions and procedures and shall be accomplished in accordance with these instructions and procedures.

Cooper Nuclear Station Administrative Procedure 1.11, "Requisitioning, Receiving, Storage of Essential Parts and Components," Revision 16, approved January 7, 1981, requires the following:

1. Sections 1.11.4.3.8 and 1.11.4.4 require verification of compliance of the material, part, or component and required documentation with purchase order requirements and documentation of this inspection on the receiving report.
2. Sections 1.11.6.1.1 and 1.11.6.1.2 require for "CNS Stores Requisitions" the following:
 - a. Completion by the requisitioner of the work document description.
 - b. Completion by the storekeeper of the material status.