

LER

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
THE HARTFORD ELECTRIC LIGHT COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
WESTERN WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

P.O. BOX 270
HARTFORD, CONNECTICUT 06101
(203) 666-6911

September 11, 1981
MP-2-4096



Mr. Ronald C. Haynes
Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-65
Docket No. 50-336
Reportable Occurrence R0-50-336/81-15/3L-1

Dear Mr. Haynes:

This letter forwards the Licensee Event Report 81-15/3L-1 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in degraded mode permitted by a limiting condition for operation. This update report provides the final corrective action for the packing failure on the turbine driven auxiliary feedwater pump. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

E. J. Mrocza
Station Superintendent
Millstone Nuclear Power Station

EJM/RB:bjc

Attachment: LER R0-81-15/3L-1

cc: Director, Office of Inspection and Enforcement, Washington, J.C. (30)
Director, Office of Management Information and Program Control,
Washington, D. C. (3)
U. S. Nuclear Regulatory Commission, c/o Document Management Branch,
Washington, D. C. 20555

8109210201 810911
PDR ADOCK 050C0336
S PDR

IR22
5/11