## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYTE ALL REQUIRED INFORMATION)
1 I A D A C 1 2 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 0 0 57 CAT 56
CON'T    SOURCE   GO   5   0   0   0   3   3   1   7   0   8   1   2   8   1   3   0   9   1   1   8   1   9     SOURCE   SOURCE
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [3 2   During normal operation, Containment Atmosphere Monitoring Systems (CAMS )
[0]3]   ) A and B were found to be operating without sample points having been r
eselected. Containment atmosphere was therefore not being monitored. Tec
o[s]   hnical Specification 3.6.C lists CAMS operability requirements. There ha
ve been two previous similar occurrences with the Containment Atmosphere
0 7   Monitoring System (See RO 81-029 and 81-026).
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
SEQUENTIAL OCCURRENCE REPORT TYPE NO.  17 REPORT   8   1   0   3   2   0   3   1   0   3   1   0   3    ACTION FUTURE EFFECT SHUTDOWN HOURS 22 STRANGED FORM 3UB. SUPPLIER WANUFACTURER  H 18 H 19   7   20   7   21   0   0   0   0   0   0   0   0   0
Personnel error. H/P personnel did not reselect sample points after CAMS
maintenance completed. Problem corrected within 5.5 hours by operator re
[1[2] L selection of sample points. Appro. pers. have been instructed on CAMS op
eration. Problem found during sample point selection verification previo
Lusly added to shift inst. check list. Design review has been initiated.
STATUS OPERATOR OF DISCOVERY DESCRIPTION (32)  NA OTHER STATUS (30) NETHODO OF DISCOVERY DESCRIPTION (32)  OPERATOR OBSERVATION (32)
ACTIVITY CONTENT RELEASED OF RELEASE NA AMOUNT OF ACTIVITY 35  1 6 7 3 9 10 11 NA LOCATION OF RELEASE 36
TYPE DESCRIPTION 39  1 7 0 0 0 0 0 27 Z 08 NA  7 8 9 PERSONNEL INJURIES 13
NOMBER DESCRIPTION (4) NA NA
LOSS OF OR DAMAGE TO PACILITY 43
7 8 9 10 PUBLICITY ISSUED DESCRIPTION 45  NRC USE ONLY  2 0 N 44 NA
B109280244 B10911 Arnold W. Schmich 56 69 80- PDR ADDCK 05000331 PDR 9008: 319-851-5611